

Approved For Release 2002/06/13 : CIA-RDP69B00041R001100060012-8

DATE

TOP SECRET

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO :

FROM :

ACTION:

INFO :

IN: 71370

Ops 1-10 e

TO TOP SECRET INFO 312144Z CITE 25X1A 2128.

25X1A

IMMEDIATE

INFO

25X1A

25X1A

A. BX 6734

B. FILM DUPLICATION REQUIREMENTS

C. I II III

I A 2 DP, ON

I B 1 DP, 1 DN

I C 1 DP

I L 1 DP

D. NONE

E. SECRET NOFORN

F. 30 OCT 67

G. NONE

TOP SECRET TOR: 312152Z OCT 67

TOP SECRET

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION

Approved For Release 2002/06/13 : CIA-RDP69B00041R001100060012-8

Approved For Release 2002/06/13 : CIA-RDP69B00041R001100060012-8

TOP SECRET

DATE

TO :

FROM :

ACTION:

INFO :

IN-71263

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

Handwritten signature
OPS-10

TO 25X1A INFO CITE 25X1A

TOP SECRET 310540Z CITE 1093

IMMEDIATE INFO IMMEDIATE ROUTINE

- A. BX6734
 - B. FILM EVALUATION REPORT
 - C. TYPE I/E /3203.5
 - D. FULTRON 202/MX578/1 MIN 4 SEC/78 DEGREES F
 - E. 2.50/2.68
 - F. 3404/2159-276-5-4-7/DNA
 - G. (1) GOOD
 - (2) NORMAL
 - (3) MEDIUM
 - (4) GOOD
 - (5) OPERATIONAL
 - (6) NORMAL
 - (7) OVERALL CLOUD COVERAGEC T1 40 PERCENT T2 65 PERCENT
 - H. O.N. DISPOSITION TO E.K.
- 3 DUPE POS TO NATIONAL CUSTOMERS

TOP SECRET

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION

Approved For Release 2002/06/13 : CIA-RDP69B00041R001100060012-8

IN-71263

1093

T O P S E C R E T

PAGE 2

6 DUPE POS AND 2 DUPE NEGS TO THEATER CUSTOMERS.

1. NORMAL START-UP FOR INITIAL 28 FRAMES AND SHUT-DOWN FOR LAST 10 FRAMES. DATA CHAMBERS SLANTED APPROXIMATELY 3 DEGREES TO THE LEFT OF PERPENDICULAR. DATA CHAMBER ENTERED IMAGE IN FRAMES 13, 277, 660, 827. MINUS DENSITY LINES IN ALL AFT FRAMES, 1/2" FROM LEADING EDGE AND 1 3/4" FROM LEADING EDGE. MINUS DENSITY LINE 1 1/4" FROM THE TRAILING EDGE OF FORWARD FRAME AND INTERMITTENT THROUGHOUT MISSION. DATA CHAMBER OUT OF FOCUS IN FRAME 45, 48, 525, 526, 659, 660. LOSS OF TIMING MARKS OCCURRED ON TRAILING EDGE OF FRAMES 106, 104, 475 TO 511; AND ON THE LEADING EDGE OF FRAMES 254, AND 256. RECYCLING OCCURRED IN FRAMES 478 TO 498. MINOR HANDLING EMULSION SCRATCHES THROUGHOUT MISSION. ONE EMULSION SCRATCH IN FRAMES 1 TO 75. WAS 3 1/2" FROM LEADING EDGE. HANDLING SCRATCHES ACCOMPANYING SPLICES IN FRAME 182, 183, 382, 383, 772, 773. SMALL EMULSION BREAK IN FRAME 37, 3 1/8" FROM LEADING EDGE AND MIDWAY INTO FRAME. IN FRAME 76 A SMALL EMULSION BREAK 1 1/2" FROM LEADING EDGE, 1" FROM EDGE OPPOSITE DATA CHAMBER AND AGAIN, A SMALL BREAK 4" FROM LEADING EDGE, 4 1/2" FROM EDGE OPPOSITE DATA CHAMBER.

T O P S E C R E T TOR: 311538Z OCT 67

25X1D

Approved For Release 2002/06/13 : CIA-RDP69B00041R001100060012-8

Next 1 Page(s) In Document Exempt

Approved For Release 2002/06/13 : CIA-RDP69B00041R001100060012-8